

2009 & UP-DODGE RAM 1500, INCLUDING CREWCAB (USE WITH 30035 KIT)

Read pages 2-3 of 30035 instructions before starting installation. Failure to do so could result in significant vehicle damage!

IMPORTANT NOTES FOR THIS INSTALLATION:

- 1. Tube spacer and 4 1/2" carriage bolt used to attach through forward Bed Sill (Row 2).
- 2. **Rib neck bolts will need to be pulled through access holes in frame with supplied pull wire (see below).





<u>CAUTION!</u> <u>\(\hat{\chi}\)</u>

Check for obstructions before drilling. Failure to do so could result in damaged fuel or brake lines, structural members, etc.

TOWING PRODUCTS does its best to communicate tow vehicle manufacturer changes; however, it is ultimately the responsibility of the installer to prevent damage due to installation.

z 2008, 2009, 2013, 2014 Cequent Performance	Sheet 1 of 1	58386N	08/11/14	Rev. E
----------------------------------------------	--------------	--------	----------	--------